

CONSUMER

PROTECTION



WISCONSIN
DEPARTMENT OF
AGRICULTURE,
TRADE AND
CONSUMER
PROTECTION

OFFICE LOCATION

2811 Agriculture Drive
Madison, WI 53708-8911

1-800-422-7128
608-224-4960

News

January 2014 Edition

Dear Wisconsin Children's Safety Advocates:

In December 2013, the U.S. Consumer Product Safety Commission issued a total of **19 recalls relating to products affecting children**. Attached is a summary of the releases identifying the product, the problem, and what should be done with the recalled product.

We have found that not all of the recalls are picked up by the news media as they occur. This monthly summary will give you the opportunity to review all of the children's product safety recalls for the past month. If you are interested in a complete text of the recall, double click on the hyperlink at the end of the recall description. This will direct you to the recall notice located on the CPSC website.

- Landscape Structures Recalls Oodle Swings Due to Injury Hazard [\(14-705\)](#)
- Cubetensils Children's Eating Utensils Recalled by Edoche Due to Choking Hazard [\(14-070\)](#)
- Playtex Recalls Hip Hammock Infant Carriers Due to Fall Hazard [\(14-069\)](#)
- Browning Recalls Junior Hoodie Due to Strangulation [\(14-067\)](#)
- Fox Factory Recalls Evolution Mountain Bike Suspension Forks Due to Fall Hazard [\(14-063\)](#)
- Mirage Fashions Recalls Yoki Girls Faux Leather Jackets with Drawstrings Due to Strangulation Hazard [\(14-050\)](#)
- Doodlebutt Recalls Jelly BeadZ Jumbo BeadZ and Magic Growing Fruity Fun Toys Due to Serious Ingestion Hazard [\(14-056\)](#)
- Trek Recalls Madone Bicycles Due to Crash Hazard [\(14-055\)](#)
- IKEA Recalls Children's Wall-Mounted Lamps [\(14-052\)](#)
- Ram's Imports Recalls Girls' Pink Leopard Jackets [\(14-051\)](#)
- Solowave Recalls Home Playground Tube Slides with Port Holes Due to Laceration Hazard [\(14-049\)](#)
- Academy Sports + Outdoors Recalls Girls BCG Hooded Windsuits Due to Strangulation Hazard [\(14-043\)](#)
- Wearever Girl's Hooded Jacket Sets Recalled by David's Place Due to Strangulation Hazard [\(14-040\)](#)
- Manhattan Group Recalls Baby Rattles [\(14-039\)](#)
- SRAM Recalls Derailleurs for Bicycles Due to Fall Hazard [\(14-038\)](#)
- K2 Sports Recalls Kickboards/Scooters Due to Fall Hazard [\(14-037\)](#)
- Joovy Recalls Zoom Car Seat Stroller Adapter due to Fall Hazard [\(14-072\)](#)
- Specialized Recalls Source Eleven and Source Expert Disc Bicycles Due to a Fall Hazard [\(14-073\)](#)
- Cabrinha Kiteboarding Recalls H2 Binding Due to Risk of Injury [\(14-074\)](#)

If you would like to sign up for the Keep Your Kids Safe newsletter, please subscribe at https://public.govdelivery.com/accounts/WIDATCP/subscriber/new?topic_id=WIDATCP_161 or contact Bobbi Erb at (608) 224-4955 or bobbi.erb@wisconsin.gov.

If you have any questions or want to file a complaint regarding an unsafe product, contact:

Wisconsin Department of Agriculture, Trade and Consumer Protection
Bureau of Consumer Protection
2811 Agriculture Drive
Madison, WI 53708
(800) 422-7128 (toll free in Wisconsin)

KEEP YOUR KIDS SAFE

Release Number: (#14-705) Landscape Structures Inc., of Delano, M.N., is announcing the voluntary recall of about 177 Landscape Structures' Oodle Swings. The swing frame is a double arch, comes in a variety of colors and measures 9 ½ ft. high by 13 ½ ft. long by 4 ½ ft. wide. The swing seat is an oval-shaped ring, measures 4 ft. wide by about 3 ½ ft. deep, comes in a variety of colors and is suspended from the frame by four black cables or chains. The swing seat holds as many as six children. Landscape Structures is printed on label near ground level on the frame. The swing set's model number 173592 is printed in the swing's instruction manual. "Landscape Structures" is molded in the black rubber bumper of the swing seat.girl's "Susan" Sandals.

Problem: The swing seat is suspended too close to the ground, posing an injury hazard to children who can get their legs caught underneath the swing seat.

What to do: Consumers should stop using the swings immediately and measure the distance between the bottom of the swing seat and the ground. If the distance is less than 12 ¾ inches, contact Landscape Structures for a free repair. Landscape Structures is contacting its customers directly. You can contact Landscape Structures Inc. toll-free at (888) 438-6574 from 8 a.m. to 5 p.m. CT Monday through Friday, or online at www.playlsi.com and click on U.S.

Voluntary Product Recall at the bottom of the page for more information.



<http://www.cpsc.gov/en/Recalls/Recall-Alerts/2014/Landscape-Structures-Recalls-Oodle-Swings/>

Release Number: (#14-070) Edoche, Inc., of Seattle, W.A., has announced the voluntary recall of about 1,100 Edoche's *Cubetensils* sets of children's eating utensils. Each set consists of a spoon and a matching fork with stainless steel heads and plastic handles. The handle has three segments that rotate to create design combinations. The utensils are 5.75-inches long and were sold in seven different models/designs: alphabet, moon and stars, nature, princess, rockets, trucks and veggies. The sets come in a brown cardboard box with a clear viewing window in the front. "Edoche" is printed on the bottom of the utensils and "Stainless Steel China" is embossed on the metal heads. The phrase "Not for children under 3" appears on the back of the product's packaging.


Problem: The utensil's handle can detach, posing a choking hazard to infants.

What to do: Consumers should immediately take the utensils away from children and contact Edoche for a full refund. You can contact Edoche by calling collect (774) 295-0170 from 9 a.m. to 5 p.m. PT Monday through Friday or online at www.edoche.com then click on About Us at the top of the page for more information. Customers can also send an email to info@edoche.com.



<http://www.cpsc.gov/en/Recalls/2014/Cubetensils-Childrens-Eating-Utensils-Recalled-by-Edoche/>

Release Number: (#14-069) Playtex Products Inc., of Dover, D.E., announces the voluntary recalls about 305,000 and 36,000 in Canada Playtex Hip Hammock infant carriers. The Playtex Hip Hammock is an infant carrier designed to strap the baby against the caregiver's body at the hip. It is made of a soft, quilted fabric and intended for babies that are from 15 to 35 pounds. The child seat is attached with straps that wrap around the carrier's hips and shoulder. "Playtex Hip Hammock" is printed on a label sewn into the front of the carrier. All model numbers are being recalled. Model numbers 05300, 05301, 05302, 05306, 05307 and 05308 are sewn into the inside panel below the instructions for use. They come in basic and deluxe styles. The hip hammock's fabric is suede or ultra-suede in black or navy colors on the outside, and the inside lining is black, black and white check or burgundy. **Problem:** The buckles on the waist and shoulder straps can crack or break, posing a fall hazard to the child. **What to do:** Consumers should stop using the carrier and contact Playtex for instructions on how to return the product for a full refund. You can contact Playtex at (800) 522-8230 from 8 a.m. to 6 p.m. ET Monday through Friday or online at www.playtexproducts.com and click on [Recall](#) for more information.



<http://www.cpsc.gov/en/Recalls/2014/Playtex-Recalls-Hip-Hammock-Infant-Carriers/>

Release Number: (#14-067) Browning, of Morgan, U.T., announces the voluntary recall of about 4,300 hooded Buckmark junior sweatshirts in sizes S, M, L and XL. The sweatshirts are made of polyester fabric. The camouflaged print pullover sweatshirt comes with black drawstrings and has a yellow embroidered Buckmark logo located on the front of the garment. There are pockets located near the waist. The sweatshirt has a hood, and rib knit cuffs and waist

Problem: The hooded sweatshirts have drawstrings around the neck area that pose a strangulation or an entanglement hazard to young children. In February 1996, CPSC [issued guidelines about drawstrings](#) in children's upper outerwear. In 1997, those guidelines were incorporated into a voluntary standard. Then, in July 2011, based on the guidelines and voluntary standard, CPSC issued a federal regulation. CPSC's actions demonstrate a commitment to help prevent children from strangling or getting entangled on neck and waist drawstrings in upper outerwear, such as jackets and sweatshirts.

What to do: Consumers should immediately remove the drawstrings from the hooded sweatshirts to eliminate the hazard or return the garment to Browning for a full refund. You can contact Browning Browning at (800) 727-4312 from 8 a.m. to 4:30 p.m. MT Monday through Friday, online at www.browning.com and click on Recall at the top of the page, or email at browninghoodie@browning.com for more information.



<http://www.cpsc.gov/en/Recalls/2014/Browning-Recalls-Junior-Hoodie/>

Release Number: (#14-063) Fox Factory, of Watsonville, C.A., is announcing the voluntary recall of about 11,250 in the U.S. and 1,250 in Canada suspension forks are model year 2013, 32 and 34 Evolution Series with 120mm to 160mm of travel. The Evolution name and logo are on a sticker on the front fork with the FOX brand name logo. Recalled forks can be identified by the serial number, which is found on the underside of the crown after removing the front wheel. The forks were sold as original equipment on some of the following 2013 model year mountain bikes: BMC, Cannondale, Commencal, Diamondback, GT, Kona, Lapierre, Norco, Orbea, Raleigh, Rocky Mountain, Santa Cruz, Scott, Specialized and Trek. A small quantity of suspension forks were sold to retailers or distributors as aftermarket accessories.

Problem: The suspension fork's damper cylinder/piston can separate and cause the front wheel to detach, posing a fall hazard.

What to do: Consumers should stop using the bicycles with recalled Fox Factory suspension forks and bring them to the place of purchase for a free repair. Consumers can check their serial number at www.ridefox.com/, see the link at the lower left of the page, or contact Fox for assistance with discerning whether their bicycle has the recalled product and for instructions on how to return the recalled product and receive the free repair if they cannot bring their bicycle or fork to the place of purchase. You can contact FOX toll-free at (855) 360-3488 from 8 a.m. to 5 p.m. PT Monday through Friday or online at www.ridefox.com and click on the recall link for more information.



<http://www.cpsc.gov/en/Recalls/2014/Fox-Factory-Recalls-Evolution-Mountain-Bike-Suspension-Forks/>

Release Number: (#14-050) Mirage Fashions of N.Y., is announcing the voluntary recall of about 758 girl's hooded faux leather jackets with a zipper front closure and bearing a Yoki Girls label at the neck. They were sold in girl's sizes 7 through 16. The jacket comes in black or charcoal, with drawstrings through the neck area. The coats have snap button pockets on each side and a zippered pocket on the top left chest area. Both the black and charcoal colored jackets have a grey hood. Style number JK2503G is on the product care label located on the lower left inside seam.

Problem: The jackets have a drawstring through the hood which can pose a strangulation hazard to children. In February 1996, CPSC issued [guidelines about drawstrings](#) in children's upper outerwear. In 1997, those guidelines were incorporated into a voluntary standard. Then, in July 2011, based on the guidelines and voluntary standard, CPSC issued a federal regulation. CPSC's actions demonstrate a commitment to help prevent children from strangling or getting entangled on neck and waist drawstrings in upper outerwear, such as jackets and sweatshirts.

What to do: Consumers should immediately remove the drawstrings from the garment to eliminate the hazard or return the garment to Mirage Fashions for a full refund. You can contact Mirage Fashion's toll-free at (855) 221-5888 from 9:00 a.m. to 3:00 p.m. ET Monday through Friday or by e-mail at Recalls@yokisport.com for additional recall information.



<http://www.cpsc.gov/en/Recalls/2014/Mirage-Fashions-Recalls-Yoki-Girls-Faux-Leather-Jackets-with-Drawstrings/>

Release Number: (#14-056) Doodlebutt, Lehigh Acres, F.L., is announcing the voluntary recall of about 1,500 Doodlebutt Jelly BeadZ Jumbo BeadZ and Magic Growing Fruity Fun water-absorbing polymer toys. The toys can absorb from 300 to 500 times their weight in water and can grow up to eight times their original size.

Problem: These soft and colorful products can be mistaken by a child for candy. When swallowed, they can expand inside a child's body and cause intestinal obstructions, resulting in severe discomfort, vomiting, dehydration and could be life threatening. Similar toys have not shown up on x-rays and needed surgery to be removed from the body.

What to do: Consumers should immediately stop using the recalled polymer products and take them away from small children. Consumers should contact Doodlebutt for a full refund. You can contact Doodlebutt, collect at (239) 313-9779 from 9 a.m. to 5 p.m. ET Monday through Friday or at e-mail whitmana@live.com.



<http://www.cpsc.gov/en/Recalls/2014/Doodlebutt-Recalls-Jelly-BeadZ-Jumbo-BeadZ-and-Magic-Growing-Fruity-Fun-Toys/>

Release Number: (#14-055) Trek Bicycles Corp., of Waterloo, W.I., is announcing the voluntary recall of about 6,800 2013 Trek Madone bicycles with model numbers 5.2, 5.9, 6.2, 6.5, 7.7 or 7.9, and serial numbers starting with WTU and ending with G or H. A list of all serial numbers included in the recall is at www.trek bikes.com. Some of the recalled models are custom-ordered Project One

Madones. The model number is printed on the bicycle frame. The serial number is printed on a sticker underneath the frame of the bicycle. The bicycles were sold in a variety of colors.

Problem: The bicycle's front brake can fail, posing a crash hazard.

What to do: Consumers should immediately stop using the recalled bicycles and take the bicycles to a Trek dealer for a free replacement front brake system. You can contact Trek at (800) 373-4594 from 8 a.m. through 6 p.m. CT Monday through Friday, or online at www.trek bikes.com and click on Safety and Recalls at the bottom of the page for more information.



<http://www.cpsc.gov/en/Recalls/2014/Trek-Recalls-Madone-Bicycles/>

Release Number: (#14-052) The U.S. Consumer Product Safety Commission (CPSC), in cooperation with IKEA North America, of Conshohocken, Pa., is announcing the recall for repair of children's wall-mounted lamps due to a strangulation hazard. A 16-month-old child in a crib died after getting entangled in the lamp's cord. In a separate incident, a 15-month-old child in a crib became entangled in the lamp's cord and nearly strangled. In both incidents, which occurred in Europe, the lamp cord was pulled into the crib by the infants. There were 2.9 million of the recalled lamps sold in the United States. In addition, 1.1 million were sold in Canada. There was a total of 23 million sold worldwide.

Problem: A 16-month-old child in a crib died after getting entangled in the lamp's cord. In a separate incident, a 15-month-old child in a crib became entangled in the lamp's cord and nearly strangled. In both incidents, which occurred in Europe, the lamp cord was pulled into the crib by the infants, creating a strangulation hazard.

What to do: Consumers should immediately stop using the recalled lamp and contact IKEA for a free repair kit. Do not use the lamp until the repair kit is installed. The repair kit has self-adhesive fasteners for attaching the lamp's cord to the wall as well as safety instructions. Contact IKEA toll-free at (888) 966-4532 anytime or online at www.ikea-usa.com and click on the

Recall link at the top of the page for more information.



<http://www.cpsc.gov/en/Recalls/2014/IKEA-Recalls-Childrens-Wall-Mounted-Lamps/>

Release Number: (#14-051) Ram's Imports Inc. of New York, N.Y., is announcing the voluntary recall of about 756 girls pink hooded jackets. The jacket is 97 % cotton 3% spandex. The jackets have pink and black leopard print drawstrings and pink and black leopard print on the sides of the jacket. "IQ girls" is printed on the sewn-in label located on the back of the neck. The model number included in the recall is 86557 and can be found printed on a sewn in label in the back of the neck. This recall involves jacket sizes girls 4 through 12.

Problem: The jackets have a drawstring through the hood which can pose a strangulation hazard to children. In February 1996, CPSC issued [guidelines about drawstrings](#) in children's upper outerwear. In 1997, those guidelines were incorporated into a voluntary standard. Then, in July 2011, based on the guidelines and voluntary standard, CPSC issued a federal regulation. CPSC's actions demonstrate a commitment to help prevent children from strangling or getting entangled on neck and waist drawstrings in upper outerwear, such as jackets and sweatshirts.

What to do: Consumers should immediately remove the drawstrings from the garment to eliminate the hazard or return the garment to Ram's Imports Inc. for a full refund. You can contact Ram's Imports toll-free at (855) 346-5950 between 10 a.m. and 5 p.m. ET Monday through Friday or online at www.ramsimports.com and click on "product recall" for additional information.



<http://www.cpsc.gov/en/Recalls/2014/Rams-Imports-Recalls-Girls-Pink-Leopard-Jackets/>

Release Number: (#14-051) Solowave Design Corp., of Hamburg, N.Y., is announcing the voluntary recall of about 10,800 in the U.S. and 9,900 in Canada Solowave Tornado brand home playground tube slides with port holes. The slides are green, six or seven feet long and have three or five port hole-style plastic windows in the sides. The slides were sold with Solowave's Centennial, Centennial II, Lexington, Rocky Mountain Deluxe and Sheridan play systems and were also sold separately. Solowave Design is stamped on the outside of the slides near the middle of each tube slide section.

Problem: The plastic port hole-type windows in the tube slide can break, posing a laceration hazard to children.

What to do: Consumers should stop using the recalled slide immediately and contact Solowave to receive a free repair kit for the port hole windows. You can contact Solowave toll-free at (866) 678-0376 between 9 a.m. and 5 p.m. ET Monday through Friday, or online at www.solowavedesign.com and click on Important Safety Notice for more information.



<http://www.cpsc.gov/en/Recalls/2014/Solowave-Recalls-Home-Playground-Tube-Slides-with-Port-Holes/>

Release Number: (#14-043) Academy Sports + Outdoors, of Katy, T.X., is announcing the voluntary recall of about 6,600 Girls BCG Hooded Windsuits in sizes XS, S, M and L. The windsuits are made of water-resistant fabric and include a jacket and pants. The jacket has a front zip closure and elastic cuffs. The windsuits come in pink with black on the jacket at the top shoulder and a black side strip on the pants, gray with blue on the jacket at the top shoulder and a blue side strip on the pants, and purple with lighter purple on the jacket at the top shoulder and a pink strip on the pants.

Problem: The hooded windsuits have drawstrings in the hood around the neck area that pose a strangulation hazard to young children. In February 1996, CPSC issued guidelines about drawstrings in children's upper outerwear. In 1997, those guidelines were incorporated into a voluntary standard. Then, in July 2011, based on the guidelines and voluntary standard, CPSC issued a federal regulation. CPSC's actions demonstrate a commitment to help prevent children from strangling or getting entangled on neck and waist drawstrings in upper outerwear, such as jackets and sweatshirts.

What to do: Consumers should immediately remove the drawstring from the windsuits to eliminate the hazard, or return the garment to the place of purchase for a full refund. You can contact Academy Sports + Outdoors toll-free at (888) 922-2336, from 8 a.m. to 10 p.m. CT Monday through Saturday and from 9 a.m. to 8 p.m. CT on Sunday, or online at www.academy.com and click on Product Recall Info for more information.



<http://www.cpsc.gov/en/Recalls/2014/Academy-Sports-Outdoors-Recalls-Girls-BCG-Hooded-Windsuits/>

Release Number: (#14-040) David's Place Off Price Clothing Co. Inc., a division of YMI Jeans, of Los Angeles, C.A. announces the voluntary recall of about 60 Wearever Girl brand girl's long

sleeve zip-up 100% cotton hooded jackets sold as a set with brown pants. The brown hooded jackets have thin aqua, light pink and light green horizontal stripes and sold in girl's sizes 7 to 16. There is a brown, flat drawstring around the neck of the jackets. "Wearever Girl" is printed on a label on the back inside neck of the jackets and on the pants.

Problem: The jackets sold with the set have drawstrings through the hood which pose a strangulation hazard to young children. In February 1996, CPSC issued guidelines for children's upper outerwear. In 1997, those guidelines were incorporated into a voluntary standard. Then, in July 2011, based on the guidelines and voluntary standard, CPSC issued a federal regulation. CPSC's actions demonstrate a commitment to help prevent children from strangling or getting entangled on neck and waist drawstrings in upper outerwear, such as jackets and sweatshirts.

What to do: Consumers should immediately take the jackets away from children and remove the drawstrings to eliminate the hazard. Consumers can also contact David's Place to obtain a return address label and instructions for returning the garment for a full refund. You can contact David's Place Off Price Clothing toll-free at (888) 394-1398 from 8:30 a.m. to 5 p.m. PT Monday through Friday or e-mail at daniala@ymijean.com for more information.



<http://www.cpsc.gov/en/Recalls/2014/Wearever-Girls-Hooded-Jacket-Sets-Recalled-by-Davids-Place/>

Release Number: (#14-039) Manhattan Group LLC, of Minneapolis, M.N., announces the voluntary recall of about 8,300 in the U.S. and 4,100 in Canada Manhattan Toy® Quixel™ baby rattle. The plastic rattles have four, colored arches (red, orange, green and blue) with sliding beads on each of the arches. The arches are held together by a single string of red, white and blue elastic. The rattle arches measure about 5 inches in diameter. The product was sold with or without a box. "Manhattan Toy" is printed on one of the arches.

Problem: The colored arches can break, creating a small part which poses a choking hazard to small children.

What to do: Consumers should immediately take these rattles away from young children and return it to the store where purchased for a full refund. You can contact the Manhattan Group at (800) 541-1345 from 8 a.m. to 5 p.m. CT Monday through Friday, or online at www.manhattantoy.com and click on RECALLS at the bottom of the home page for more information.



<http://www.cpsc.gov/en/Recalls/2014/Manhattan-Group-Recalls-Baby-Rattles/>

Release Number: (#14-038) SRAM, LLC, of Chicago, I.L., announces the voluntary recall of about 1,700 SRAM RED WiFLi Rear Derailleur is a device that moves a bicycle chain gears on the rear wheel. The name SRAM RED and the serial number of the derailleur are located on the back of the inner pulley wheel cage plate and visible when looking thru the spokes of the bicycle wheel.

Problem: The rear derailleur's rear pivot pin can loosen or dislodge causing the rear derailleur to jam or interfere with the wheel, posing a fall hazard.

What to do: Consumers should immediately stop using bicycles with the recalled SRAM RED derailleur and return the bicycles to the place of purchase or any SRAM dealer for a free replacement, including installation. Consumers who bought the derailleur as a stand-alone product can take them to the place of purchase for a free replacement or, for those who can make the equipment change themselves, contact SRAM for instructions on how to return the recalled product for the free replacement. You can contact SRAM at (800) 346-2928 between 9 a.m. and 5 p.m. Monday through Friday CT or online at www.sram.com and click on "Recall Information" for more information.



<http://www.cpsc.gov/en/Recalls/2014/SRAM-Recalls-Derailleurs-for-Bicycles/>

Release Number: (#14-037) K2 Sports, of Seattle, W.A., announce the voluntary recall of about 400 K2 Revo Kick kickboards/scooters with item code I10700100. Revo Kick and the item code are printed on a sticker on the underside of the deck. The kickboard/scooter is made of aluminum, has three wheels, a wooden deck and a vertical handle with a round grip. The kickboards/scooters measure about 32 inches long and 40 inches high. The deck has a red, white and blue design with K2 printed on it.

Problem: The front assembly of the kickboards/scooters can break and the handle can detach or partially detach, causing loss of control or loss of balance. This poses a fall hazard to the rider.

What to do: Consumers should immediately stop using the recalled kickboards/scooters and contact K2 Sports for a full refund. You can contact K2 Sports toll-free at (866) 302-9996 from 7 a.m. to 5 p.m. PT Monday through Friday, email the firm at kickboard@k2sports.com or online at www.k2sports.com and click on Important Safety Information for more information.



<http://www.cpsc.gov/en/Recalls/2014/K2-Sports-Recalls-Kickboard-Scooters/>

Release Number: (#14-072) Joovy's is announcing the voluntary recall of about 1,500 Joovy's Zoom gray metal car seat stroller adapters. The adapters are gray with black plastic clips designed to attach infant car seats to stroller frames. The adapter frame's dimensions are approximately 17" x 13" x 10". Recalled car seat adapter models include 00945 for Graco, 00946 for Chicco and 00947 for Peg Perego frames. "Joovy" and the model numbers can be found on the label at the center of the end bar of the adapter.

Problem: Adapter clips can loosen on the stroller frame, posing a fall hazard.

What to do: Consumers should stop using these adapters and contact Joovy for a free repair kit to help assure proper attachment to Zoom stroller frames. You can contact Joovy toll-free at (855) 251-0759 from 8 a.m. to 5 p.m. CT Monday through Friday or online at www.joovy.com, then click on the "Customer Service" menu at the top of the page, then select "Recall Information" for more information.



<http://www.cpsc.gov/en/Recalls/2014/Joovy-Recalls-Zoom-Car-Seat-Stroller-Adapter/>

Release Number: (#14-073) Specialized Bicycle Components, Inc., of Morgan Hill, C.A., is announcing the voluntary recall of about 173 2012 model year Source Eleven and Source Expert Disc bicycles with Supernova Switchable Dynamo Front Hubs as part of the original equipment. The name "Specialized" is printed on the bicycle's down tube and "Source Eleven" or "Source Expert" are printed on the top tube. The front hubs have "www.supernova-lights.com" and one of the following model numbers printed on them: 1207, 1208, 1226, 1227, 1228, 1241, 1254, 1263, 1284 and 1344.

Problem: The set screws in the front hub of the recalled bicycles can loosen and stop the front wheel from turning, posing a fall hazard to consumers.

What to do: Customers should immediately stop riding the recalled bicycles and bring them to an authorized Specialized dealer for a free

replacement front wheel and new Supernova front hub. For a list of authorized dealers go to www.specialized.com/ and click on Dealers in the upper right hand corner of the page. You can contact Specialized Bicycle Components, Inc. toll-free at (877) 808-8154 from 8 a.m. to 4:30 p.m. PT Monday through Friday or online at www.specialized.com and click on "Safety/Recalls" at the bottom of the page for more information.



<http://www.cpsc.gov/en/Recalls/2014/Specialized-Recalls-Source-Eleven-and-Source-Expert-Disc-Bicycles/>

Release Number: (#14-074) Adventure Sports Inc., dba Pryde Group Americas, of Miami, F.L., is announcing the voluntary recall of about 57 in the U.S. and 5 in Canada the standard size H2 Hydra Series Binding. The binding mounts on the twintip style kiteboards and is used to connect the rider by his feet to the board. The H2 binding is blue and black and has dual adjusting straps with 'Cabrinha' and 'H2' on the footstrap. The product was manufactured in June and July 2013. The H2 binding comes in two sizes: standard and small. The product code is KB4H2BDSL which is found on the retail packaging.

Problem: The binding can detach from its base while riding and lead to loss of control, which poses a risk of injury.

What to do: Consumers should immediately stop using the recalled binding and contact any Cabrinha authorized dealer for a free replacement binding. A list of authorized dealers can be found at www.cabrinhakites.com/dealers.html, You can contact Pryde Group Americas by sending an e-mail to support@cabrinhakites.com, or by calling Pryde Group Americas (PGA) collect at (305) 591-3922 from 9:30 a.m. to 6:30 p.m. ET Monday through Friday or online at www.cabrinhakites.com and click on Safety Alert under the Support tab at the top of the page for more information.



<http://www.cpsc.gov/en/Recalls/2014/Cabrinha-Kiteboarding-Recalls-H2-Binding/>